

Lecciones aprendidas de terremotos recientes: Ideas para la evolución de los códigos de diseño sísmico

Lessons from recent earthquakes: thoughts for seismic design codes evolution

Humberto Varum, A. Arêde, A. Furtado, H. Rodrigues, J. Melo
 hvarum@fe.up.pt

Contents

Risk: General concepts and Seismic risk

Lessons from recent earthquakes and common damages in RC building structures

Construction practices: Past and Present

LESE activities: Performance assessment and retrofitting of RC structures

Final comments

Contents

Risk: General concepts and Seismic risk


Lessons from recent earthquakes and common damages in RC building structures

Construction practices: Past and Present

LESE activities: Performance assessment and retrofitting of RC structures

Final comments


Natural Disasters: Occurrences



(Munich Re, 2012)

- Geophysical events (including earthquakes) are constant throughout the years
- Meteorological events have increased in the last years

Natural Disasters: Economical Losses



(Munich Re, 2012)

- Natural disasters are more frequent now than 30 years ago, and are costing us much more

Risk ?

Risk can be defined as the likelihood or probability of a given hazard of a given level causing a particular level of loss or damage. (Alexander, Confronting catastrophe, 2000)

Examples of Natural Disasters
affecting our society:

Avalanches

Earthquakes

Fires

Volcanic eruptions

Hydrological disasters (Floods, Tsunami)

Meteorological disasters (Blizzards, Tornados)

Wildfires

Health disasters (Epidemics)

Space disasters

...

Seismic Risk (is the “product” of three vectors) “=”

Hazard
Probability of...

“x”

Vulnerability
Engineering

“x”

Exposure
... of values




Lower Risk



Higher Risk

Solutions to mitigate the seismic risk: (1) Better characterization of hazard; (2) Reduce the vulnerability of the constructions through engineering; (3) Develop a land-use planning strategy, avoiding the development of big cities and important infrastructures in seismically active regions.

Earthquakes with $M > 6$ and Losses $> 10,000$ M USD between 1985 and 2011




Strong earthquakes with great economic impact happen in every continent.

(Romão, 2012)

Seismic Hazard

Several Megacities are located in areas with high seismic hazard.



(Global Seismic Hazard Assessment Program, 2010)

Contents

Risk: General concepts and Seismic risk

Lessons from recent earthquakes and common damages in RC building structures

Construction practices: Past and Present

LESE activities: Performance assessment and retrofitting of RC structures

Final comments

Initial considerations...

Do we know everything about the effect of earthquakes in the response of building structures, particularly regarding the influence of IM walls?


Can we continue designing/assessing our structures ignoring the influence of IM walls (so-called “non-structural” elements)?

Even if we include in our next generation of design codes the most advanced and state-of-the-art knowledge, how can we deal with the seismic risk associated with the vast existing building stock?


In the last decades, a large number of new materials and solutions were introduced in the construction of buildings' envelopes. How they will behave in the future earthquakes?




Emilia Romagna, Italy, 2012




Emilia Romagna, Italy, 2012



Until 2003 Emilia Romagna region was not considered a seismic zone, and the structures were designed without seismic concerns





Emilia Romagna, Italy




Emilia-Romagna

Until 2003 Emilia Romagna region was not considered a seismic zone, and the structures were designed without seismic concerns



Emilia Romagna, Italy, 2012



Bologna – May 20 and 29, 2012


Magnitude 6.1-5.8

26 deaths and 43,000 homeless

Economic loss of \$13,000M US



Ischia, Italy, August 2017



Ischia – August 21, 2017

Magnitude 4.2

2 deaths, 42 Injured

2,600 homeless



The Magnitude was relatively low, but the energy, hypocentric depth, propagation and soil response and the building vulnerability may justify the level of damage observed.

Damages in RC building structures

Eurocode 8 (EN 1998-1:2004) definitions


Structural elements

- i) Primary members (SP): Members considered as part of the structural system that resist the seismic demands, modelled in the analysis for the seismic design situation and fully designed and detailed for earthquake resistance according to the specific rules of EN 1998.
- ii) Secondary members (SS): Members which are not considered as part of the seismic action resisting system and whose strength and stiffness against seismic actions is neglected; they are not required to comply with all the rules of EN 1998, but are designed and detailed to maintain support of gravity loads when subjected to the displacements caused by the seismic design condition.



Non-structural elements (NS)

Architectural, mechanical or electrical element, system and component which, whether due to lack of strength or to the way it is connected to the structure, is not considered in the seismic design as load carrying element.



Damages in RC building structures



Structural: Primary (SP) and Secondary (SS) elements



Non-Structural (NS)

Surroundings (foundations, soils, pounding,...)

Damages in RC building structures

Common damages in RC buildings

1. Stirrups and hoops (inadequate quantity and detailing, regarding the required ductility)
2. Detailing (bond, anchorage and lap-splices)
3. Inadequate capacity and failure (shear, flexural)
4. Inadequate shear capacity of the joints
5. Strong-beam weak-column mechanism
6. *Short-column* mechanism
7. Structural irregularities (in plan or in elevation: torsion , “weak-storey”, “soft-storey”)
8. Interaction and Pounding

SP

9. Damages in structural Secondary Elements (cantilivers, stairs,...)

SS

10. Damages in Non-Structural Elements

NS

Observed damages in recent earthquakes: Field evidence

L'Aquila – April 6, 2009

Magnitude **6.3**

308 deaths and 65,000 homeless

Economic loss of \$10,000M US

Bologna – May 20, 2012

Magnitude 6.1-5.8

26 deaths and 43,000 homeless

Economic loss of \$13,000M US

Ischia – August 21, 2017

Magnitude 4,2

2 deaths and 2,600 homeless

Lorca – May 11, 2011

Magnitude **5.1**

9 deaths and 5,000 homeless

Economic loss of \$99M US

Only in these earthquakes!

~20,000 deaths

~555,000 homeless

>100,000 million USD of losses

Central Italy – August 24, 2016

Magnitude 6,2

299 deaths and 4,500 homeless

Economic loss of \$11,000M US

Athens – September 7, 1999

Magnitude 6.0

143 deaths and 50,000 homeless

Economic loss of \$3,000M US

Kocaeli – August 17, 1999

Magnitude 7.5

17,127 deaths and 300,000 homeless

Economic loss of \$23,000M US

Duzce – November 12, 1999

Magnitude 7.2

894 deaths and 24,000 homeless

Economic loss \$40M US

Van – October 23, 2011

Magnitude 7.1

604 deaths and 60,000 homeless

Economic loss of \$2,000M US


Damages in RC building structures

1. Stirrups and hoops (inadequate quantity and/or detailing, regarding the required **ductility**)



Damages in RC building structures

1. Stirrups and hoops (inadequate quantity and/or detailing)



Detailing errors: hook bends at 90°

Emilia Romagna, 2012


Damages in RC building structures

2. Detailing (bond, anchorage and lap-splices)



Damages in RC building structures

2. Detailing (bond, anchorage and lap-splices)



Detailing errors: smooth plain bars, hook ends, lap-splices, hooks bends,...

2009 L'Aquila

Damages in RC building structures



3. Inadequate capacity and failure (**shear**, flexural)

General data

- Location: Petino
- year of construction: 2000
- residential building
- 10 apartments
- isolated
- ground storey + 5 storeys
- without basement
- average storey height equal to 2.5m
- RC framed structure
- with masonry infill walls



Shear failure of interior columns at the ground storey level



2009 L'Aquila

Damages in RC building structures

3. Inadequate capacity and failure (shear, flexural)




2009 L'Aquila

Insufficient amount of transverse reinforcement, and longitudinal reinforcement only in two column faces; excessive distance between *longitudinal bars* in two faces of the columns

Damages in RC building structures

4. Inadequate shear capacity of the joints



Damages in RC building structures

4. Inadequate shear capacity of the joints



Absence of hoops/stirrups in the joints; lap-splices of column reinforcing bars in the joint regions; inadequate bars anchorage



General data

- Location: Petino
- year of construction: 1982/83
- residential building
- isolated
- ground storey + 2 or 3 storeys
- without basement
- storey height: 2.4m (ground storey); 2.7m (other storeys)
- RC framed structure
- with masonry infill walls



2009 L'Aquila

Damages in RC building structures

4. Inadequate shear capacity of the joints

Deficiencies in the reinforcement detailing of beam-column joints



Absence of joint transverse reinforcement; inadequate anchorage of the beam longitudinal bars; shear failure of joints

2009 L'Aquila

Damages in RC building structures

4. Inadequate shear capacity of the joints



RC building collapse a few hours after the earthquake: various deficiencies in the beam-column joints (absence of hoops/stirrups; lap-splices of column reinforcing bars in the joint region; poor anchorage of longitudinal bars)

2011 Lorca


Damages in RC building structures

5. Strong-beam weak-column mechanism




Damages in RC building structures

5. Strong-beam weak-column mechanism





$$\sum M_{R,column} \geq \gamma_{R,d} \cdot \sum M_{R,beam}$$

Eurocode 8: $\gamma_{R,d} = 1.3$



(WHE Report)



Columns should have larger flexural capacity than beams at each joint.

Early design philosophies (pre-80s codes) did not have this mechanism hierarchy concern.

Damages in RC building structures

5. Strong-beam weak-column mechanism



General data

- Location: Petino
- year of construction: 1982/83
- residential building
- isolated
- ground storey + 2 or 3 storeys
- without basement
- storey height: 2.4m (ground storey); 2.7m (other storeys)
- RC framed structure
- with masonry infill walls



Inadequate plastic hinges hierarchy, with failures occurring first on columns

Damages in RC building structures

6. Short-column mechanism




Damages in RC building structures

6. Short-column mechanism



General data

- Location: Paganica
- year of construction: before 2000 ?
- residential building
- 8 apartments
- isolated
- ground storey + 2 storeys
- without basement
- ground storey height significantly lower than the height of the upper storeys
- RC framed structure with masonry infill walls



Openings interrupting the masonry infill walls, inducing a modification in the stress distribution along the structural elements

2009 L'Aquila

Damages in RC building structures

6. Short-column mechanism






Short-columns' shear failure: due to openings, or in columns at ground storey levels where is observed a variable ground height, associated with insufficient amount of transverse reinforcement

2011 Lorca

Damages in RC building structures

6. Short-column mechanism



RC building collapse (*pancake* type collapse) due to insufficient strength of the short-columns for the high shear force demands (due to the ground unevenness)

2011 Lorca


Damages in RC building structures

7. Structural irregularities (in plan or in elevation: torsion , “weak-storey”, “soft-storey”)



Damages in RC building structures

7. Structural irregularities (in plan or in elevation: torsion , “weak-storey”, “soft-storey”)



Structural scheme/plan (ground storey)

General data

- Location: Petino
- year of construction: 1982/83
- residential building
- isolated
- ground storey + 2 or 3 storeys
- without basement
- storey height: 2.4m (ground storey); 2.7m (other storeys)
- RC framed structure
- with masonry infill walls

Highly irregular (in terms of stiffness and strength), both in plan and in elevation:

- + Irregularities in elevation (ground storey with reduced number of walls - for garages) +
- + Irregularities in plan (torsion) +
- + Poor detailing of beam-column joints; absence of stirrups; poor concrete quality

2009 L'Aquila

Damages in RC building structures

7. Structural irregularities (in plan or in elevation: torsion , “weak-storey”, “soft-storey”)

Collapse due to soft-storey mechanism: reduced number of masonry infill walls in the ground storey, causing a significant variation of stiffness and strength in elevation, creating a “soft storey” and “weak storey” + irregularities in plan (torsion)



2009 L'Aquila

Damages in RC building structures

7. Structural irregularities (in plan or in elevation: torsion , “weak-storey”, “soft-storey”)

General data

- Several blocks built in different periods: The hospital's construction began in 1972 / One of the most recent blocks was opened in 2000
- Main and larger medical centre (Central Hospital) in the affected region, serving a region with 1800 km²
- The hospital complex has 13 independent wings, being composed by 20 buildings, including the Medical School
- Many buildings are irregular structures in plan and in elevation (3 to 5 storeys)
- RC structures (framed; some buildings have RC structural shear-walls with large dimensions)



Severe damages in the RC columns, due to pronounced irregularities in plan and in elevation

Building that gives access to the Emergency Ward - built in 2000 - 2 storeys

Damages in RC building structures

7. Structural irregularities (in plan or in elevation: torsion , “weak-storey”, “soft-storey”)

Severe damages in the RC columns, due to pronounced irregularities in plan and in elevation (induced by the structural itself + distribution of in fill masonry walls)



2009 L'Aquila

Damages in RC building structures

7. Structural irregularities (in plan or in elevation: torsion , “weak-storey”, “soft-storey”)



Flexible ground storey, convenient for commerce/services' use, inducing a pronounced irregularity in elevation

Main characteristics:



- (1) Height significantly greater than the upper storeys
- (2) Absence of masonry infill walls
- (3) Wall panels not developed along the total storey height

The walls at the ground storey often less resistant and stiff

Observed damages in recent earthquakes: Field evidence

Soft-storey mechanism (in-elevation irregularity)

- Common infill masonry panels can modify drastically the global structural behavior, attracting forces to parts of the structure that were not designed to support them, leading to unexpected behavior/response and collapse mechanisms



(Patrick Corell, 2011)

Structural design:

- Without considering the masonry walls

Real behaviour:

- Concentration of demands at the ground storey level

But... infill masonry panels are usually considered in the design of new structures as non-structural elements, and its influence in the structural response is disregarded !

Damages in RC building structures

8. Interaction and Pounding



Interaction between buildings: adjacent buildings with different heights, or with different structural and/or constructive or material solutions, in the urban centre, leading to different dynamic responses, hence boosting pounding, as well as to stress and strain demands concentration in certain points

2011 Lorca

Damages in RC building structures

9. Damages in Structural Secondary Elements



(ARTI, 2011)



(AFP, 2014)



(USGS, 1989)

Damages in RC building structures

9. Damages in Structural Secondary Elements: Stairs



Damages associated with the stairs' elements, mainly in the lower storeys. Lack of specific design of these secondary structural elements, and/or reinforcement detailing errors (design?/construction?), and/or non specific connection to the main structural system

2011 Lorca

Damages in RC building structures

10. Damages in Non-Structural Elements: infill masonry (in-plane)

Damages in masonry exterior panels




In-plane response (interface separation between infills and resistant structure, diagonal cracking, corner crushing)

2009 L'Aquila

Damages in RC building structures

10. Damages in Non-Structural Elements: infill masonry (in-plane response: diagonal cracking)



2009 L'Aquila

Damages in RC building structures

10. Damages in Non-Structural Elements: infill masonry (in-plane response)

Widespread damages in the masonry infill walls in all building of Aquila Hospital



- Significant structural damages; complete buildings' collapse did not occur
- A few hours after the earthquake, the Hospital was declared inoperative in 90% of its functions

2009 L'Aquila

Damages in RC building structures

10. Damages in Non-Structural Elements: infill masonry (out-of-plane response)

Out-of-plane failure of masonry enclosure walls



2009 L'Aquila

Damages in RC building structures

10. Damages in Non-Structural Elements: Parapets



Elements not adequately connected to the structure may fall over the street

2009 L'Aquila

Damages in RC building structures

10. Damages in Non-Structural Elements: Parapets



OOP collapse of masonry enclosure walls

(L'Áquila, Italy, 2009)

Damages in RC building structures

10. Damages in Non-Structural Elements: collapse of exterior panels in double-leaf walls

Damages in masonry exterior panels



Excessive deflection in cantilevers; large dimensions of the masonry panels; exterior panels non confined; with poor connection (to the structure and to the interior panel)

2009 L'Aquila

Damages in RC building structures

10. Damages in Non-Structural Elements: collapse of exterior panels in double-leaf walls

Damages in masonry exterior panels – Inadequate support



Possible causes: Poor connection between the exterior and interior panels (in double leaf walls), and between the exterior panel and the structural elements. Exterior panels supported on the beams/slabs, approximately, in only half panel thickness

2009 L'Aquila

Damages in RC building structures

10. Damages in Non-Structural Elements: Coatings



Poor connection of finishing/coverings (heavy pieces) glued in singular points with “cement glue”, without any mechanical fixing system

2011 Lorca

Nepal: 2015 EQs


Capital Kathmandu (largest city)

Total Area 147,181 km² (**1,6x PT**)

Population 28,120,000 (**2,7x PT**)


Density 180 /km²

GDP 19.77 USD Billion (**8% PT**)




Sources:
wikimedia.org
tradingeconomics.com

Nepal: Past strong Earthquakes (since 20th century...)




Distribution of the collapsed and damaged buildings



EXTENSIVE CATASTROPHIC DAMAGE TO PROPERTY WAS REPORTED THROUGHOUT CENTRAL NEPAL, INCLUDING KATHMANDU

Distribution of the collapsed and damaged buildings



EXTENSIVE CATASTROPHIC DAMAGE TO PROPERTY WAS REPORTED THROUGHOUT CENTRAL NEPAL, INCLUDING KATHMANDU

Adobe buildings: sun-dried bricks with mud mortar



Stone masonry with mud mortar: plastered or non-plastered



Brick masonry with mud mortar: fired bricks




Stone masonry with cement mortar:
plastered or non-plastered



Brick masonry with cement mortar:
fired bricks





The 2011 census data shows that mud-bonded brick and stone (BM&SM) buildings were more popular in Nepal (~45%), followed by wooden constructions, and by cement-bonded brick and stone buildings (BC&SC).


In urban areas, cement-bonded brick and stone (BC&SC) buildings represents ~35%. About 29% of the buildings in urban areas are reinforced concrete structures.


In Kathmandu valley, 38% of the buildings were constructed with RC framed structures, followed by BC&SC and BM&SM.

Over the last few decades (1991-2001), RC building construction has rapidly increased, replacing other construction materials and solutions, like adobe, stone and brick masonry, in Kathmandu Valley.

Most RC buildings in Nepal were constructed with framed structures with infill masonry panels. These buildings offered insufficient capacity, lacked ductile detailing and were poorly constructed and may have limited durability.

Chaulagain, Rodrigues, Varum (2014)







Non-Engineered Reinforced Concrete Moment-Resisting-Frame buildings

These are the buildings with RC elements and unreinforced brick masonry walls with cement mortar joints. The prevalent practice in most urban areas of Nepal for the construction of residential and commercial complexes generally falls under this category. These buildings are not structurally designed and supervised during construction by engineers.



Engineered Reinforced Concrete Moment-Resisting-Frame buildings

These buildings consist of a frame assembly of cast-in-situ concrete beams and columns. Floor and roof elements consist of cast-in-situ concrete slabs. Lateral forces are resisted by RC moment frames that develop their stiffness through monolithic beam-column connections. For these engineered buildings, the structural design and construction supervision is made by engineers.

NEPAL 2015 EQs - SURVEY DAMAGE ASSESSMENT

RC structures with infill walls



DEFICIENT RC STRUCTURAL SYSTEMS | SOLID BRICKS INFILL WALLS WITH POOR MORTAR JOINTS

NEPAL 2015 EQs - SURVEY DAMAGE ASSESSMENT

RC structures with infill walls



SOFT-STOREY MECHANISMS | IN-ELEVATION IRREGULARITY | FAILURE OF COLUMNS

NEPAL 2015 EQs - SURVEY DAMAGE ASSESSMENT

RC structures with infill walls



SOFT-STOREY MECHANISMS | IN-ELEVATION IRREGULARITIES | 3+ ADDED STOREYS

NEPAL 2015 EQs - SURVEY DAMAGE ASSESSMENT

RC structures with infill walls



COLUMNS/JOINTS SHEAR FAILURE | POOR DETAILING | INADEQUATE BARS' ANCHORAGE AND INSUFFICIENT STIRRUPS | POOR MATERIALS QUALITY

NEPAL 2015 EQs - SURVEY DAMAGE ASSESSMENT

RC structures with infill walls



MEDIUM-RISE BUILDING | SEVERE DAMAGES CONCENTRATED IN SOME COLUMNS AT GROUND LEVEL | IN-PLAN IRREGULARITY (ONLY-ONE FULL INFILLED FAÇADE)

NEPAL 2015 EQs - SURVEY DAMAGE ASSESSMENT

RC structures with infill walls



MEDIUM-RISE BUILDING | SEVERE DAMAGES CONCENTRATED IN SOME COLUMNS AT GROUND LEVEL | IN-PLAN IRREGULARITY (ONLY-ONE FULL INFILLED FAÇADE)

NEPAL 2015 EQs - SURVEY DAMAGE ASSESSMENT

RC structures with infill walls



MEDIUM-RISE BUILDINGS | STRONG INFILL WALLS | SHEAR SLIDING MECHANISM AND DAMAGE IN ADJACENT COLUMNS (SHEAR-OUT)

NEPAL 2015 EQs - SURVEY DAMAGE ASSESSMENT

RC structures with infill walls



MEDIUM-RISE BUILDINGS | POOR QUALITY OF CONCRETE | SHEAR-OUT

NEPAL 2015 EQs - SURVEY DAMAGE ASSESSMENT

RC structures with infill walls



POOR QUALITY OF MATERIALS AND CONSTRUCTION DETAILING

NEPAL 2015 EQs - SURVEY DAMAGE ASSESSMENT

RC structures with infill walls



INADEQUATE CAPACITY OF COLUMNS | DIMENSIONS AND DETAILING | SOFT-STOREY

NEPAL 2015 EQs - SURVEY DAMAGE ASSESSMENT

RC structures with infill walls



INSUFFICIENT CAPACITY OF RC ELEMENTS | DIMENSIONS AND DETAILING | SOFT-STOREY | STIRRUPS FAILURE

NEPAL 2015 EQs - SURVEY DAMAGE ASSESSMENT

High-Rise RC structures with infill walls



HIGH-RISE WDS BUILDINGS

DAMAGES ESSENTIALLY AT NON-STRUCTURAL ELEMENTS

NEPAL 2015 EQs - SURVEY DAMAGE ASSESSMENT

High-Rise RC structures with infill walls



PRONOUNCED IN-PLANE CRACKING | OUT-OF-PLANE COLLAPSE OF WALLS

FINAL REMARKS

RC building structures

- **Non EQ-designed** structures suffered extensive damage and partial or full collapses, mostly due to vertical irregularities
- **Well-designed** RC buildings demonstrated significant non-structural damage
- Insufficient control by Nepalese entities (design and construction)



URM buildings

- Extensive damage and collapses are attributed to poor materials and inadequate construction detailing/practices
- Weak connections between the walls and floors/roof, which do not guarantee a proper demand distribution/transfer and stability



Historical buildings

- Slender monumental structures, such as towers and temples, presented higher level of damage



2017 Central Mexico earthquake (19th Sep.)

RC building structures – Observed damages

Weak columns (section size, insufficient transversal reinforcement, poor detailing)

Flat slab

Pounding

Poor material properties

Short-column mechanisms...

But ...

Irregularities (in-elevation and in-plan) in terms of stiffness/strength due to drastic changes in the structural and/or IM walls configuration (location and number of infill walls):


Soft/Weak-storey mechanism

Torsion

IM walls in Mexico

Masonry units


Different masonry units are used to construct IM walls: solid, perforated unit, hollow unit, cellular unit and horizontally perforated



Rivero, J. (2002), "Manual técnico de construcción"

IM walls in Mexico

Confined masonry walls and IM walls



2017 Central Mexico earthquake (19th Sep.)

RC building structures – Observed damages

Structural configuration problems were a major cause of failure, or severe damage. Most configuration problems were associated with the contribution of non-structural elements to the building response, especially in corner buildings where two perpendicular facades were fully infilled with masonry walls, and the facades facing the street were left open.





2017 Central Mexico earthquake (19th Sep.)

RC building structures – Observed damages



IM walls



Jean Ingenieros (2017)

IP damages:

- diagonal cracking;
- detachment from the surrounding frame

OOP collapse:

- IP-OOP interaction



Damages in RC building structures

Common damages in RC buildings

1. Stirrups and hoops (inadequate quantity and detailing, regarding the required ductility)
2. Detailing (bond, anchorage and lap-splices)
3. Inadequate capacity and failure (shear, flexural)
4. Inadequate shear capacity of the joints
5. Strong-beam weak-column mechanism
6. *Short-column* mechanism
7. Structural irregularities (in plan or in elevation: torsion , “weak-storey”, “soft-storey”)
8. Interaction and Pounding
9. Damages in structural Secondary Elements (cantilivers, stairs,...)
10. Damages in Non-Structural Elements

SP

← INT

SS

NS

Damages in RC building structures



Structural: Primary (SP)
and Secondary (SS)
elements



INTERACTION
(INT)



Non-Structural
(NS)

Surroundings (foundations, soils, pounding,...)

Damages in RC building structures

Main conclusions and lessons from the recent earthquakes

- (1) **Structural damage** are mainly present in **columns** and beam-column **joints**, due to the **design philosophy** and **poor** reinforcement **detailing**, according to old design codes
- (2) **Many buildings were severely damaged or collapsed due to the irregularities**, in plan or in elevation (ground storey used for commerce), induced by both structural and/or non-structural elements
- (3) **Most damages in buildings comes from non-structural elements**, such as infill walls
- (4) **Non-structural elements** with very **poor performance**, causing **major economic losses** and some **deaths** (detachment and collapse of exterior panels in façade masonry walls)

This evidences the influence of the “non-structural” elements, like masonry infill walls, in the structural behaviour and performance of RC buildings

Contents

Risk: General concepts and Seismic risk


Lessons from recent earthquakes and common damages in RC building structures

Construction practices: Past and Present

LESE activities: Performance assessment and retrofitting of RC structures

Final comments




Evolution of exterior Masonry walls in Southern Europe (Portugal, ...)



- The type of units and the dimensions and detailing of infill walls have been influenced by the emerging requirements in terms of thermal and acoustical performance
- Associated to these new requirements, new solutions and materials were also introduced: perforated clay bricks, isolating layers, air gaps, “*thermal*” blocks, etc.
- The connection of the infill walls with the main structural system and between internal and external layers was progressively improved
- In any case, up to a recent past, these “non-structural” elements were generally disregarded in the structural design and analysis of buildings. Their behavior and influence in the seismic structural response was considered negligible or, wrongly, it was commonly assumed that if “*...they influence the structural response and safety, it is in its benefit!*”

Masonry units of common use

Construction practice in Southern European regions (Portugal,...)



Current design and construction practice

In some Southern European regions, the following solutions are nowadays commonly adopted in façade walls:

- horizontal-hole bricks (with more than 60% of voids)
- double or single masonry panels, confined by the RC structural elements
- without connection to the main structure
- absence of connectors between panels
- correction of thermal bridges with mechanically unstable solutions



Even when the constructive details for the walls construction are provided, they basically consist of typified solutions for common situations, without giving particular attention to the singular points

Current construction practice

IN masonry walls with horizontal hollow clay bricks:



How these buildings will perform in the next earthquakes?

Current construction practice

IN masonry walls with horizontal hollow clay bricks:



How these buildings will perform in the next earthquakes?

Current construction practice



IN masonry walls with different types of units:



Bare Frame RC structure – Stage 1



RC structure with different types of IM walls – Stage 2

How these buildings will perform in the next earthquakes?

Current construction practice

IN masonry walls with vertical hollow concrete blocks:



How these buildings will perform in the next earthquakes?

Contents

Risk: General concepts and Seismic risk

Lessons from recent earthquakes and common damages in RC building structures

Construction practices: Past and Present

LESE activities: Performance assessment and retrofitting of RC structures

Final comments

Seismic assessment of RC structures




Existing buildings (1950s, 1960s, ...) and New construction

1983 – RSA/REBAP // Eurocodes (EC8)

Seismic assessment of RC structures

LESE activities



- **RC structural System**
 - RC columns (biaxial tests with a w/o retrofit)
 - RC Beam-column joints (tests with and w/o retrofit)
 - Numerical modelling
- **Infill Masonry Walls**
 - Geometric characterization
 - Mechanical characterization tests
 - Ambient vibration tests
 - Cyclic OOP tests with and without previous damage
 - Numerical modelling

Seismic assessment of RC structures

LESE activities



- **RC structural System**
 - RC columns (biaxial tests with a w/o retrofit)
 - RC Beam-column joints (tests with and w/o retrofit)
 - Numerical modelling
- **Infill Masonry Walls**
 - Geometric characterization
 - Mechanical characterization tests
 - Ambient vibration tests
 - Cyclic OOP tests with and without previous damage
 - Numerical modelling

Seismic assessment of RC columns



In the last years, the LESE group have carried out a large number of uniaxial and biaxial experimental tests on as-built and retrofitted RC columns

- More than 45 biaxial tests under constant or variable axial load and different lateral displacement paths
- More than 100 uniaxial tests under constant or variable axial load



Seismic assessment of RC columns

Test Setup



Seismic assessment of RC columns

Retrofitting solutions

Retrofitting solutions

Realistic repair and retrofitting solutions were developed and tested




- Steel plates wrapping
- CFRP wrapping
- Concrete jacketing
- External longitudinal reinforcement



Seismic assessment of RC beam-column joints

Test Setup

- The specimens are tested in the horizontal position
- Sliding devices at the beam extremities were used to simulate the beams support conditions
- Two hydraulic actuators for the axial load and one servo-actuator to impose the lateral displacements at the top of the column




Seismic assessment of RC beam-column joints

Retrofitting solutions


Realistic retrofitting solutions were developed and tested for RC beam-column joints with transversal beams and slab

- Steel plates wrapping
- CFRP wrapping
- Concrete jacking


Top column



Bottom column




Activities of LESE




- **RC structural System**
 - RC columns (biaxial tests with and w/o retrofit)
 - RC Beam-column joints (tests with and w/o retrofit)
 - Numerical modelling
- **Infill Masonry Walls**
 - Geometric characterization
 - Mechanical characterization tests
 - Ambient vibration tests
 - Cyclic OOP tests with and without previous damage
 - Numerical modelling

Activities of LESE





Geometric characterization of the masonry infill walls



Geometric characterization of the masonry infill walls

Main results:

- Majority of existing RC buildings were constructed between 1965 and 1995
- 40% of the buildings were designed without seismic concerns or for low seismic demands




- 73% of the buildings analyzed have a residential use-only, and the others have multiple use (residential, offices and/or commercial stores).




Geometric characterization of the masonry infill walls

Main results:




Activities of LESE



In-situ characterization on masonry walls

Main Goals

- Calibration of numerical models
- Damage detection for post-earthquake rehabilitations
- In-situ and laboratory testing



In-situ characterization on masonry walls

Main Goals

- Existing buildings, but also in buildings under construction
- different: typologies; panel dimensions; openings dimensions and locations; border support conditions; ...





Furtado A., Rodrigues H., Arêde A., Varum H. (2017) – Modal identification of infill masonry walls with different characteristics, *Engineering Structures*, Vol. 145, PP. 118-134

In-situ characterization on masonry walls

Evolution of building natural frequencies: Building B

- 4 storeys building
- Horizontal hollow clay bricks




$f_x=2.93\text{Hz}$ $f_y=2.93\text{Hz}$

$f_x=3.42\text{Hz}$ $f_y=3.42\text{Hz}$

$f_x=3.91\text{Hz}$ $f_y=3.42\text{Hz}$

Activities of LESE



Experimental characterization of masonry walls mechanical properties



Different types of masonry units were developed and introduced in the construction, throughout the last decades, pushed by the architectural requirements, comfort and energy efficiency concerns/requirements, or aiming at the use of innovative green materials and solutions.

Mechanical characterization tests

Compression strength tests: main results




$F_{m,brick11}=0.7\text{MPa}$
 $SD:0.1\text{MPa}$ COV: **18,8%**
 $E_{m,brick11}=855\text{MPa}$
 $SD:332\text{MPa}$ COV:39%



$F_{m,brick15}=1.1\text{MPa}$
 $SD:0.1\text{MPa}$ COV: **11,3%**
 $E_{m,brick15}=942\text{MPa}$
 $SD:233\text{MPa}$ COV:24,8%

Hollow clay brick

- Fragile behaviour
- Larger dispersion




$F_{m,concrete31.5}=1.9\text{MPa}$
 $SD:0.1\text{MPa}$ COV: **5,1%**
 $E_{m,concrete31.5}=2304\text{MPa}$
 $SD:115\text{MPa}$ COV:5.1%

$F_{m,concreteAzores}=2.4\text{MPa}$
 $SD:0.1\text{MPa}$ COV: **3,8%**
 $E_{m,concreteAzores}=3855\text{MPa}$
 $SD:165\text{MPa}$ COV:4,8%


Concrete block

Mechanical characterization tests

Diagonal compression strength tests: main results



$F_{m,brick11} = 0.5\text{MPa}$
SD:0.2MPa COV:34,7%
 $G_{,brick11} = 1068\text{MPa}$
SD:76.6MPa COV:7,2%



$F_{m,brick15} = 0.6\text{MPa}$
SD:0.1MPa COV:20,1%
 $G_{,brick15} = 925.5\text{MPa}$
SD:36.6MPa COV:4,1%



$F_{m,concrete31.5} = 0.3\text{MPa}$
SD:0.1MPa COV:21,7%
 $G_{,concrete31.5} = 1472\text{MPa}$
SD:630MPa COV:42,9%


$F_{m,concreteAzores} = 0.4\text{MPa}$
SD:0.1MPa COV:33,3%
 $G_{,concreteAzores} = 1867\text{MPa}$
SD:402MPa COV:16%

Concrete block wallets


- Similar failure pattern
- High dependence of the mortar-block interface

Mechanical characterization tests


Flexural tests (parallel to bed-joints joints): main results



$F_{xi,brick11}=0.12\text{MPa}$
SD:0.005MPa COV:3,9%



$F_{xi,brick15}=0.11\text{MPa}$
SD:0.047MPa COV:4.3%



$F_{xi,concrete31.5}=0.10\text{MPa}$
SD:0.019MPa COV:18,8%
 $F_{xi,concreteAzores}=0.25\text{MPa}$
SD:0.09MPa COV:33,8%

- Similar failure pattern
(detachment between block and joint)
- High dependence of the brick/block-joint
interface

Mechanical characterization tests

Flexural tests (perpendicular to bed-joints joints): main results



$F_{xij,brick11}=0.32\text{MPa}$
 $SD:0.061\text{MPa COV:19,9\%}$




$F_{xij,brick15}=0.38\text{MPa}$
 $SD:0.036\text{MPa COV:9,9\%}$

- Similar failure pattern
- Dependence of the masonry unit holes direction



$F_{xi,concrete31.5}=0.12\text{MPa}$
 $SD:0.03\text{MPa COV:24.7\%}$
 $F_{xi,concreteAzores}=0.32\text{MPa}$
 $SD:0.05\text{MPa COV:14,1\%}$

Activities of LESE




Full-scale OOP tests of IM walls

Objectives of the OOP testing campaign on full-scale IM specimens

- Characterization of the out-of-plane behaviour of full-scale IM walls (with and without previous in-plane damage)
- Development of an innovative out-of-plane experimental test setup
- Development, study and validation of retrofitting solutions

Full-scale OOP tests of IM walls

Testing platform: 2nd phase (pneumatic actuators) – General views



→ Project ASPASSI, reference PTDC/ECM-EST/3790/2014, FCT (2016-2018); Partners: FEUP (Leader), UM and LNEC.



LESE

Laboratório de Engenharia Sísmica e Estrutural

Full-scale OOP tests of IM walls

Influence of retrofitting (GFRP mesh with connectors)



Inf_07	Cyclic	As-built
Inf_08	Cyclic	Retrofitted

Final Damage state

As-built
(max OOP disp. 30mm)




Retrofitted
(max OOP disp. 70mm)



Activities of LESE

- In-plane behavior models
- Case studies
- Consideration of the OOP behavior (IP and OOP interaction curve; removal algorithm)



Case studies: modelling the in-plane behavior of infills



Costa-Cabral, 1953

- Rectangular geometry in-plan ($37.2 \times 16.4 \text{ m}^2$)
- 8 stories
- 4 longitudinal frames (X)
- 10 transverse frames (Y)
- Technical story between the ground story and the 1st story



Parnaso, 1955

- Rectangular in-plan geometry ($26.2 \times 9.9 \text{ m}^2$)
- 6 stories
- 3 longitudinal frames (X)
- Stairs isolated from the housing block by an expansion joint



Infante Santo, 1954

- Rectangular in-plan geometry ($46.1 \times 11.1 \text{ m}^2$)
- 9 stories
- 12 transverse frames (Y)
- Non-infilled ground-story

Location



Contents

Risk: General concepts and Seismic risk

Lessons from recent earthquakes and common damages in RC building structures

Construction practices: Past and Present

LESE activities: Performance assessment and retrofitting of RC structures


Final comments

Code requirements

Eurocode 8 (2004) recommendations/requirements

EC8 highlight the following principles regarding the structural conception/design:

- Structural simplicity
- Uniformity, symmetry and redundancy
- Bi-directional strength and stiffness
- Torsional resistance and stiffness
- Rigid diaphragm at storey level
- Adequate foundations



Those principles should influence the structural system configuration definition. If they are followed associated with the remaining code dispositions and requirements, structures will tend to perform better for the expected earthquake demands.

Code requirements

Eurocode 8 (2004) recommendations/requirements

Ductility classes

- Low ductility (DCL): only recommended for regions with low seismicity, where the design is based on provisions from Eurocode 2. This type of structure is designed to sustain seismic action within elastic range. In seismic regions, it is not recommended for design for other DCs, with provisions aimed at ensuring a high capacity to dissipate energy at specific building critical locations.

IM walls with high potential influence

- Medium ductility (DCM)
 - High ductility (DCH)
- should not have any type of brittle failure in any element

Code requirements

Requirements for design and detailing of RC elements

Table 2.5: General performance recommendations according to the different ductility classes by Eurocode 8 [CEN, 2003; Fardis, 2009].

General	DCL	DCM	DCH
Concrete:	none	> C16/20	> C20/25
Steel:	Ductility class B or C	Class B or C	Class C
Steel conditions:	EC2	Ribbed bars (except closed stirrups and cross-ties)	Ribbed bars (except closed stirrups and cross-ties)
Steel overstrength:	none	none	$f_{yk,0.95} \leq 1.25f_{yk}$
Beams	DCL	DCM	DCH
Dimensions	-	$b_w \leq \min(8v + h_w; 2h_x)$	$b_w \leq \min(8v + h_w; 2h_x)$ $b \geq 200\text{mm}$ $b/h \geq 0.25$
Design forces	Structural Analysis	V_{Ed} with extreme moments	V_{Ed} with extreme moments
Strength	EC2 ($1 \leq \cot \theta \leq 2.5$)	$\gamma_{Rd} = 1.0$ EC2 ($1 \leq \cot \theta \leq 2.5$)	$\gamma_{Rd} = 1.2$ EC2 ($1 \leq \cot \theta \leq 2.5$) (*)
Critical region (CR)	h_w	h_w	$1.5h_w$
Min. long. reinf.	$\rho_{min} = 0.26f_{ctm}/f_{yk} \geq 0.13\%$	$\rho_{min} = 0.5f_{ctm}/f_{yk}$	$\rho_{min} = 0.5f_{ctm}/f_{yk}$
Min. long. reinf.	-	$A_{inf} \geq 0.5A_{sup}$	$A_{min,inf} = A_{max,inf}/4$ $A_{inf} \geq 0.5A_{sup}$ $A_{min,inf} = A_{min,inf} - 2\phi 14$
Max. long. reinf.	$\rho_{max} = 4\%$	$\rho_{max} = \rho' + 0.0018f_{cd}/(\mu_0 \sigma_{yk} f_{yk})$	$\rho_{max} = \rho' + 0.0018f_{cd}/(\mu_0 \sigma_{yk} f_{yk})$
Interior joints	-	$d_{st}/h_x \leq 7.5f_{ctm}(1 + 0.8v_d)/(f_{yd}(1 + 0.5\rho'/\rho_{max}))$	$d_{st}/h_x \leq 6.25f_{ctm}(1 + 0.8v_d)/(f_{yd}(1 + 0.75\rho'/\rho_{max}))$
Exterior joints	-	$d_{st}/h_x \leq 7.5f_{ctm}(1 + 0.8v_d)/(f_{yd})$	$d_{st}/h_x \leq 6.25f_{ctm}(1 + 0.8v_d)/(f_{yd})$
Out of CR	$\rho_w \leq 0.75$ $\rho_w 0.08 \sqrt{f_{ck}/f_{yk}}$	$\rho_w 0.08 \sqrt{f_{ck}/f_{yk}}$	$\rho_w 0.08 \sqrt{f_{ck}/f_{yk}}$
In CR	$d_{st} \geq 8\text{mm}$	$d_{st} \geq 8\text{mm}$ $s_w \leq \min(h_w/4; 24d_{st}; 225\text{mm}; 8d_{st})$	$d_{st} \geq 8\text{mm}$ $s_w \leq \min(h_w/4; 24d_{st}; 175\text{mm}; 8d_{st})$
Columns	DCL	DCM	DCH
Dimensions	-	$b_x \geq h_x/10$ if $\theta(-F_S/V_h) > 0.1$	$b_x \geq 25\text{cm}$ $b_x \geq h_x/10$ if $\theta(-F_S/V_h) > 0.1$
Forces	Structural Analysis	$\gamma_{Rd}=1.3$, M_{Ed} from beams' M_{Rd}	$\gamma_{Rd}=1.3$, M_{Ed} from beams' M_{Rd}
Ultimate strength	EC2	$\gamma_{Rd}=1.1$, V_{Ed} from column extremities' M_{Rd}	$\gamma_{Rd}=1.3$, V_{Ed} from column extremities' M_{Rd}
Biaxial bending	EC2	EC2 ($\theta_d \leq 0.85$)	EC2 ($\theta_d \leq 0.55$)
Critical region	$l_{cr} = \max(h_x; h_y)$	Biaxial bending or simplified uniaxial bending with $M_{Rd} + M_{Rd}$ reduced in 30%	Biaxial bending or simplified uniaxial bending with $M_{Rd} + M_{Rd}$ reduced in 30%
Min. long. reinf. (longitudinal)	$\rho_{min} = 0.01N_d/A_c f_{yk} \geq 0.2\%$	$l_{cr} = \max(h_x; h_y; l_0/6; 45\text{cm})$	$l_{cr} = \max(1.5h_x; 1.5h_y; l_0/6; 60\text{cm})$
Long. bars per side	≥ 2	$\rho_{min} = 1.0\%$, symmetric	$\rho_{min} = 1.0\%$, symmetric
Spacing between restrained bars	-	≥ 3	≥ 3
Distance of unrestrained bar from Max. long. reinf.	-	$\leq 200\text{mm}$	$\leq 150\text{mm}$
Longitudinal bar diameter	$\rho_{max} = 4\%$ $d_{st} \geq 8\text{mm}$	$\rho_{max} = 4\%$ $d_{st} \geq 8\text{mm}$	$\rho_{max} = 4\%$ $d_{st} \geq 8\text{mm}$
Transv. reinf. in CR	-	$d_{st} \geq 8\text{mm}$ $s_w \leq \min(b_x/2; 175\text{mm}; 8d_{st})$	$d_{st} \geq 0.4d_{st, max} \sqrt{f_{yd}/f_{ywd}}$ $s_w \leq \min(b_x/3; 125\text{mm}; 6d_{st})$
Transv. reinf. out of CR	$d_{st} \geq \max(d_{st}/4; 6\text{mm})$ $s_w \leq \min(20d_{st}/40\text{cm}; \min(h_x; h_y))$	$d_{st} \geq \max(d_{st}/4; 6\text{mm})$ $s_w \leq \min(20d_{st}/40\text{cm}; \min(h_x; h_y))$	$d_{st} \geq \max(d_{st}/4; 6\text{mm})$ $s_w \leq \min(20d_{st}/40\text{cm}; \min(h_x; h_y))$
Confinement in CR	-	$d_{st} \geq 8\text{mm}$ $s_w \leq \min(h_x/2; 175\text{mm}; 8d_{st})$	$\omega_{wd} \geq 30\mu_0 \sigma_{yk} s_w (b_c/b_0) - 0.035$ $\omega_{wd} \geq 0.08$
Confin. bottom of columns	-	$\omega_{wd} \geq 20\mu_0 (\sigma_d + \omega_s) s_{y,d} (b_c/b_0) - 0.035$ $\omega_{wd} \geq 0.08$	$\omega_{wd} \geq 30\mu_0 (\sigma_d + \omega_s) s_{y,d} (b_c/b_0) - 0.035$ $\omega_{wd} \geq 0.12$

Code requirements

Requirements for design of building considering the IM walls influence

Table 2.7: Seismic standards on masonry infilled RC frames (adapted from [Kaushik *et al.*, 2006] and [Nazief, 2014]).

Country & Reference	D	Natural period	Min. force (%)		Irregularity		K	Drift	σ_1	Infill		
			Frame	Inf	Plan	Elev.				K_1	O	OOP
Albania [KTP-N2-89, 1989]	Y		N	N	N	N	1.2-1.5	N	N	N	N	N
Algeria [RPA, 1988]	Y	$*r_{eq} \vee T_u = \min \left\{ 0.09 \frac{h}{\sqrt{A_1}}, 0.05h^{0.75} \right\}$	25	N	N	N	1.42	N	N	N	N	N
Bulgaria [BGSC, 1987]	Y	X	N	N	N	Y	1.5-3.0	N	N	N		
Canada [CSA-S304.1, 2004]	-	-	-	-	-	-	Y	-	-	-	-	-
China [GBJ-11, 1989]	Y	X	N	N	N	N	Y					
Colombia [NSR, 1998]	Y	$*r_{eq} \vee T_u = C_t h^{0.75} \quad C_t = \frac{0.75}{\sqrt{A_1}}$ $A_1 = \sum A_i \left(0.2 + \min \left\{ \left(\frac{l_{wi}}{h} \right)^2, 0.9 \right\} \right)^2 \quad (m)$ $T_u = 0.08N \text{ (infilled)} \mid T_u = 0.1N \text{ (bare)}$	28	100	N							
Costa Rica [CFIA, 1986]	Y		25									
Egypt [ECP, 1988]	Y	$T_u = 0.09 \frac{h}{\sqrt{A_1}}$										
Ethiopia [ESCP-1, 1983]	Y	$T_u = 0.09 \frac{h}{\sqrt{A_1}}$										
Europe [CEN, 2003]	Y											
France [AEC-1, 1981]												
India [IS-1893, 2000]												
Venezuela [COVENIN-2002, 1988]	Y	Rayleigh formula ($*r_{eq}$) $T_u = 2\pi \sqrt{\left(\sum_{i=1}^N W_i \delta_{i1}^2 \right) / \left(g \sum_{i=1}^N F_i \delta_{i1} \right)}$	25	N	N	N	X	N	N	N	N	N
Only standard [FEMA, 1998]	Y	X	N	N	N	N	X	Y	Y	Y	Y	Y

D (dynamic analysis for irregular buildings), K (ratio for design forces MI-RC), σ_1 (strength of infill), K_1 (stiffness of infill), O (consider openings of infill)

C_t (correction factor for masonry infill), l_{wi} (length of the wall i in the first storey), A_1 (cross-section area of the wall),

A_{eq} (combined effective area of masonry infill in the first storey), h (height of the building), - (no information yet).

In many codes coexist: a rigorous set of rules and requirements for the design and detailing of RC structures, and their elements, with simplified, or even totally absence, of rules taking into account the influence of IN in the response of the building structures, and to their detailing!

Timeline of Eurocodes

1984 - The first Eurocodes were published by the Commission

1990 - ENVs started, following a Mandate issued in 1989 by the EC and the MS. The preparation and publication of the Eurocodes was transferred to CEN. The Eurocodes were intended to become European Standards

1992 - Publication of ENV Eurocodes by CEN begun

1998 - Conversion of ENV to EN was initiated following the Commission Mandate to CEN

2004 - The Directive on Public Works contracts, Public Supply contracts and Public Service contracts was issued

2007 - The Publication of EN Eurocodes was **concluded**

..... - on-going a new revision of the Eurocodes ...



Final comments

In the assessment of existing buildings, and in the design of new buildings...

- consideration of the IM walls in the structural design (based on simple checking rules/procedures after the structural design) should be enforced
- particular attention should be given to:
 - irregularities in-elevation (as in the stiffness differences between the 1st and the upper storeys: storey height, dimensions and position of openings, distribution of IM walls)
 - irregularities in-plan: torsion
 - influence of plain reinforcing bars
 - reinforcement detailing (beam-column joints, transverse reinforcement in the columns, and anchorage of the longitudinal reinforcing bars of the columns and beams)
- The OOP collapse of infills can result in serious **human** and **material consequences**, as observed in recent earthquakes. So, there is a need to consider the OOP behavior of IM walls in the seismic safety assessment of existing RC structures.

Acknowledgments

André Furtado

Hugo Rodrigues

António Arêde

Valdemar Luís

Nuno Pinto

Guilherme Nogueira

Catarina Costa

Armando Borges

Leonardo Pereira

Patrícia Raposo

António Carvalheira

Miguel Pinho

Aníbal Costa

...




Project POCI-01-0145-FEDER-007457 - CONSTRUCT - Institute of R&D in Structures and Construction funded by FEDER funds through COMPETE2020 - Programa Operacional Competitividade e Internacionalização (POCI) and by national funds through FCT - Fundação para a Ciência e a Tecnologia, Portugal.

Experimental research was developed under financial support provided by FCT - Fundação para a Ciência e Tecnologia, Portugal, namely through the research project POCI-01-0145-FEDER-016898 e PTDC/ECM-EST/3790/2014 – ASPASSI - Safety Evaluation and Retrofitting of Infill masonry enclosure Walls for Seismic demands.



Lesson...



“Earthquakes don't kill, buildings do...”

rpee

<http://rpee.lnec.pt/>



revista portuguesa de
engenharia de estruturas
portuguese journal of structural engineering



Revista científica e técnica desde 1978
Scientific journal since 1978

Artigos em português, inglês ou castelhano
Portuguese, English or Spanish Articles

Periodicidade quadrimestral
Published quarterly

Em indexação internacional
Under international indexation

Submissão de artigos
Article submission
<http://rpee.lnec.pt/submission>



<http://rpee.lnec.pt/>

U. PORTO
FEUP FACULDADE DE ENGENHARIA
UNIVERSIDADE DO PORTO

 **CONSTRUCT**


LABORATÓRIO NACIONAL
DE ENGENHARIA CIVIL


Associação Portuguesa
de Engenharia de Estruturas

 **GPBE**
Grupo
Português
de Betão
Estrutural

 **SOCIEDADE
PORTUGUESA DE
ENGENHARIA
SÍSMICA**

MASTERS AND
PhD PROGRAMS
IN CIVIL
ENGINEERING

DOCTORAL
PROGRAMME IN
SPATIAL
PLANNING

DOCTORAL
PROGRAMME IN
CIVIL
ENGINEERING

MASTER
PROGRAMME IN
SPATIAL
PLANNING AND
URBAN PROJECT

MASTER IN
URBAN MOBILITY
MANAGEMENT



MASTER IN SOIL
MECHANICS AND
GEOTECHNICAL
ENGINEERING



MASTER IN CIVIL
ENGINEERING
STRUCTURES



MASTER IN
ADVANCED
STUDIES IN
BUILDING
REHABILITATION



MASTER IN CIVIL
ENGINEERING



MASTER
PROGRAMME
IN INTEGRATED
BUILDING
DESIGN AND
CONSTRUCTION



MASTER IN CIVIL ENGINEERING

1 st Year, 1 st Semester	Credits	1 st Year, 2 nd Semester	Credits
Mathematical Analysis I	7,0	Mathematical Analysis II	7,0
Algebra	7,0	Numerical Analysis	6,0
Technical Drawing	6,5	Topography	6,0
Computation	6,0	Mechanics 1	7,0
History of Civil Engineering	2,0	Economics and Management	4,0
Project FEUP	1,5		
Total	30	Total	30
2 nd Year, 1 st Semester	Credits	2 nd Year, 2 nd Semester	Credits
Mathematical Analysis III	5,5	Statistics	6,5
Environmental and Social Assessment	4,5	Architecture	5,5
Mechanics 2	6,0	Physics	5,0
Engineering Geology	6,0	General Hydraulics I	5,0
Strength of Materials I	8,0	Strength of Materials II	8,0
Total	30,0	Total	30,0
3 rd Year, 1 st Semester	Credits	3 rd Year, 2 nd Semester	Credits
Construction Materials I	5,5	Construction Materials II	5,5
Structural Analysis I	7,0	Structural Analysis II	7,0
General Hydraulics II	6,5	Hydrology and Water Resources	6,5
Physic of Constructions	6,0	Technology of Construction	5,5
Operational Research	5,0	Territorial Planning	5,5
Total	30,0	Total	30,0
4 th Year, 1 st Semester	Credits	4 th Year, 2 nd Semester	Credits
Structural Concrete I	8,0	Structural Concrete II	8,0
Soil Mechanics I	7,0	Soil Mechanics II	6,0
Environmental and Urban Hydraulics	6,5	Urban Environment and Transport Planning	5,0
Roads I	5,5	Roads II	6,5
Project Management	3,0	Construction Management and Safety	4,5
Total	30,0	Total	30,0

MASTER IN CIVIL ENGINEERING

Materials and Construction Processes			
5 th Year, 1 st Semester	Credits	5 th Year, 2 nd Semester	Credits
Materials Pathologies	5,0	Thesis in Materials and Construction Processes	30,0
Application Geosynthetics in Civil Engineering	5,0		
Construction with New Materials	5,0		
Construction Processes	5,0		
Prefabrication	5,0		
Construction Monitoring and Observation	5,0		
Structures			
5 th Year, 1 st Semester	Credits	5 th Year, 2 nd Semester	Credits
Advanced Structural Analysis	5,0	Thesis in Structures	30,0
Structural Dynamics and Earthquake Engineering	5,0		
Prestressed Structures	5,0		
Steel and Composite Structures	5,0		
Bridges	5,0		
Foundations and Retaining Structures	5,0		
Geotechnics			
5 th Year, 1 st Semester	Credits	5 th Year, 2 nd Semester	Credits
Foundations	5,0	Thesis in Geotechnics	30,0
Models and Safety in Geotechnics	5,0		
Numerical Methods in Geotechnics	5,0		
Earth Retaining Structures	5,0		
Embankment Works	5,0		
Underground Works	5,0		
Territory Planning and Environment			
5 th Year, 1 st Semester	Credits	5 th Year, 2 nd Semester	Credits
Planning and Environmental Quality	5,0	Thesis in Territory Planning and Environment	30,0
Urban Planning	5,0		
Planning and Mobility Management	5,0		
Regional Planning	5,0		
Urban Management	5,0		
Transport Systems	5,0		

MASTER IN CIVIL ENGINEERING STRUCTURES

1 st Year, 1 st Semester	Study hours	Contact contact/week	Credits
Numerical Methods in Structural Analysis	162	56 ^{TP}	6
Structural Safety and Risk Analysis	162	56 ^{TP}	6
Design of Concrete Structures	162	56 ^{TP}	6
Soil and Structural Dynamics	162	56 ^{TP}	6
Foundations	162	56 ^{TP}	6
1 st Year, 2 nd Semester			
Project 1	162	56 ^{TP}	6
Steel and Composite Structures	162	56 ^{TP}	6
Non-Linear Structural Analysis (optional)	162	56 ^{TP}	6
Seismic Engineering & Wind Engineering (optional)	162	56 ^{TP}	6
Prestressed Structures (optional)	162	56 ^{TP}	6
Masonry and Timber Structures (optional)	162	56 ^{TP}	6
Earth Support Structures (optional)	162	56 ^{TP}	6
Underground Works (optional)	162	56 ^{TP}	6
2 nd Year, 1 st Semester			
Project 2	162	56 ^{TP}	6
Recycled Materials in Structures and Geotechnics	162	56 ^{TP}	6
Advanced Structural Materials (optional)	162	56 ^{TP}	6
Bridges (optional)	162	56 ^{TP}	6
Pre Fabricated Structures (optional)	162	56 ^{TP}	6
Rehabilitation of Structures & Foundations (optional)	162	56 ^{TP}	6
Landfill Works (optional)	162	56 ^{TP}	6
Instrumentation & Monitoring of Works (optional)	162	56 ^{TP}	6
Any UPorto 2nd Cycle Course Unit (optional)	162	-	6
2 nd Year, 2 nd Semester			
Dissertation	810	14 ^{TP}	30

DOCTORAL PROGRAMME IN CIVIL ENGINEERING

Course unit	Study hours	Contact contact/week	Credits
Civil Engineering Course Units - Branch	540(d)	T/TG: 180 (d)	10 a 30
Civil Engineering Course Units	135 (e)	T/OT/PL: 45 (e)	0 a 10
Non-Civil Engineering Course Units	135 (f)	T/OT: 45 (f)	0 a 10
Research Thesis Project	810	OT: 80	30
Original Thesis	3240	OT: 320	120

Notes

(a) – To choose from the range of course units included in the table below, in the Civil Engineering scientific area - Specialism chosen;

(b) – To choose from the range of course units included in the table below, in the different Civil Engineering scientific sub-areas and any other course units taught in other civil engineering doctoral programmes at any other Portuguese or foreign university, on approval by the Programme Scientific Committee;

(c) – To choose from any course units taught at the UP outside the scope of the Civil Engineering Doctoral Programme (including those offered in the table below as OUT), and any other course units taught in other doctoral programmes at any other Portuguese or foreign university, on approval by the Programme Scientific Committee;


(d) – Calculation for 20 ECTS;

(e) – Calculation for 5 ECTS;

(f) – Calculation for 5 ECTS.



www.fe.up.pt/dec



INSTITUTO DA
CONSTRUÇÃO

Gracias por
Vuestra atención!

Humberto Varum

hvarum@fe.up.pt

